



**Think Oil Bond Claim, Vaughn #1, API No. 05-081-05332**

Date: 12-12-2014

Photographer: David Andrews

Facing: north

Description: Unused equipment and wellhead.



**Think Oil Bond Claim, Vaughn #1, API No. 05-081-05332**

Date: 12-12-2014

Photographer: David Andrews

Facing: northeast

Description: Wellhead in a depression with staining around wellhead.



**Think Oil Bond Claim, Vaughn #1, API No. 05-081-05332**

Date: 12-12-2014

Photographer: David Andrews

Facing: east

Description: Unused equipment and wellhead.



**Think Oil Bond Claim, Vaughn #1, API No. 05-081-05332**

Date: 12-12-2014

Photographer: David Andrews

Facing: south

Description: Unused equipment and wellhead.



**Think Oil Bond Claim, Vaughn #1, API No. 05-081-05332**

Date: 12-12-2014

Photographer: David Andrews

Facing: southwest

Description: Unused equipment and wellhead.



**Think Oil Bond Claim, Vaughn #1, API No. 05-081-05332**

Date: 12-12-2014

Photographer: David Andrews

Facing: northwest

Description: Unused equipment and wellhead.



**Think Oil Bond Claim, Vaughn #1, API No. 05-081-05332**

Date: 12-12-2014

Photographer: David Andrews

Facing: southeast

Description: Access.



**Think Oil Bond Claim, Vaughn #1, API No. 05-081-05332**

Date: 12-12-2014

Photographer: David Andrews

Facing: northwest

Description: Access.