

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:
12/29/2014

Document Number:
668500754

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

| | | | | | |
|---------------------|---------------|---------------|---------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>252901</u> | <u>303318</u> | <u>Welsh, Brian</u> | <input type="checkbox"/> | |

Operator Information:

| | |
|-----------------------|-------------------------------------|
| OGCC Operator Number: | <u>72118</u> |
| Name of Operator: | <u>PRIME OPERATING COMPANY</u> |
| Address: | <u>9821 KATY FREEWAY STE 1050</u> |
| City: | <u>HOUSTON TX</u> Zip: <u>77042</u> |

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|----------------------------|------------------------|---------|
| ROELFS, TOM | 785-332-0374 cell/78110 | tom.roelfs@adtrigs.com | |

Compliance Summary:

QtrQtr: SESE Sec: 12 Twp: 4S Range: 44W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 10/24/2012 | 663901888 | PR | PR | SATISFACTORY | | | No |
| 11/22/2011 | 663900119 | PR | PR | ALLEGED VIOLATION | P | | Yes |
| 05/17/2011 | 200310566 | PR | PR | ACTION REQUIRED | | | Yes |
| 03/07/2011 | 200300045 | PR | PR | ACTION REQUIRED | | | Yes |
| 06/18/2008 | 200191387 | PR | PR | SATISFACTORY | | | No |
| 08/29/2003 | 200043129 | PR | PR | SATISFACTORY | | Pass | No |
| 07/11/2001 | 200019276 | PR | PR | SATISFACTORY | | Pass | No |

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|--|
| 252901 | WELL | PR | 06/22/1983 | GW | 125-06777 | COOK 16-12 | PR <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Lease Road: | | | | |
|--------------------|------------------------------|-----------------------------|-------------------|------|
| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
| Access | SATISFACTORY | TWO TRACKTHROUGH FARMGROUND | | |

| Signs/Marker: | | | | |
|----------------------|------------------------------|----------------------------------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| TANK LABELS/PLACARDS | SATISFACTORY | METAL SIGN BY WATER TANK | | |
| WELLHEAD | SATISFACTORY | LEASE SIGN MOUNTED ON METER SHED | | |

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Fencing/: | | | | |
|------------------|------------------------------|---|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| PUMP JACK | SATISFACTORY | METAL FENCE AROUND UNIT, WELLHEAD, VGS AND METER SHED | | |

| Equipment: | | | | | |
|---------------------|---|------------------------------|---|-------------------|---------|
| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| Gas Meter Run | 1 | SATISFACTORY | | | |
| Ancillary equipment | 1 | SATISFACTORY | ELECTRIC PANEL | | |
| Prime Mover | 1 | SATISFACTORY | ELECTRIC MOTOR | | |
| Vertical Separator | 1 | SATISFACTORY | VERTICAL GAS SEPARATOR 50% BURIED BY METER SHED | | |
| Pump Jack | 1 | SATISFACTORY | JENSEN UNIT | | |

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|----------------|---|----------|----------------|-----------------------|
| PRODUCED WATER | 1 | 200 BBLS | PBV FIBERGLASS | 39.719010,-102.237980 |

S/A/V: SATISFACTORY Comment: FIBERGLASS WATER TANK 50% BURIED

Corrective Action: _____ Corrective Date: _____

Paint

Condition: _____

Other (Content) _____

Inspector Name: Welsh, Brian

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------------------|----------|---------------------|---------------------|-----------------|
| | | | | |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

| Venting: | |
|-----------------|---------|
| Yes/No | Comment |
| NO | |

| Flaring: | | | | |
|-----------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 252901

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 252901 Type: WELL API Number: 125-06777 Status: PR Insp. Status: PR

Producing Well

Comment: PRODUCING. CASING PRODUCTION

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Pass Recontoured Pass Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Inspector Name: Welsh, Brian

Comment: UNUSED AREAS OF LOCATION ARE FARM GROUND

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |
| Gravel | Pass | | | | | |

S/A/V: SATISFACTOR Corrective Date: _____
Y _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT