


OG12 Facility

Inspection# 675201043

Sign on tank missing capacity.



Unused equipment.



Rutting on location

