

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400667792

Date Received:

08/19/2014

Spill report taken by:

CANFIELD, CHRIS

Spill/Release Point ID:

438658

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u>	Operator No: <u>100185</u>	Phone Numbers
Address: <u>370 17TH ST STE 1700</u>		Phone: <u>(303) 774-3980</u>
City: <u>DENVER</u>	State: <u>CO</u>	Mobile: <u>(970) 397-9558</u>
Zip: <u>80202-5632</u>		Email: <u>blake.ford@encana.com</u>
Contact Person: <u>Blake Ford</u>		

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400666816

Initial Report Date: 08/18/2014 Date of Discovery: 08/17/2014 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NWNE SEC 4 TWP 3N RNG 68W MERIDIAN 6Latitude: 40.261820 Longitude: -105.006770Municipality (if within municipal boundaries): _____ County: WELD

Reference Location:

Facility Type: TANK BATTERY ☒ Facility/Location ID No 426234☐ No Existing Facility or Location ID No.☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): >=100Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): 0Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: CROP LAND

Other(Specify): _____

Weather Condition: Cloudy, low 90sSurface Owner: FEE

Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On August 17th, at approximately 3:30 PM, the lease operator at Encana's Peppler Farms NWNE Battery was draining water off the bottom of the tanks into the water pits but forgot to close the valves before he left. While he was at the next site the automated emergency shutdown (ESD) alerted him of the issue. He rushed back to the site, but not before the water pits had overflowed into the lined secondary containment. He immediately shut in the wells, called a vacuum truck, and alerted on-call.

List Agencies and Other Parties Notified:

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 08/19/2014		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE			<input checked="" type="checkbox"/>
PRODUCED WATER			<input checked="" type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: _____

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) ☒ Soil ☒ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 65 Width of Impact (feet): 65

Depth of Impact (feet BGS): 3 Depth of Impact (inches BGS): _____

How was extent determined?

The extent will be determined once an environmental site assessment is conducted.

Soil/Geology Description:

Colby silty clay loam, wet, 0 to 3 percent slopes.

Depth to Groundwater (feet BGS) 3 Number Water Wells within 1/2 mile radius: 0

If less than 1 mile, distance in feet to nearest

Water Well	<u> </u>	None <input checked="" type="checkbox"/>	Surface Water	<u>70</u>	None <input type="checkbox"/>
Wetlands	<u> </u>	None <input checked="" type="checkbox"/>	Springs	<u> </u>	None <input checked="" type="checkbox"/>
Livestock	<u> </u>	None <input checked="" type="checkbox"/>	Occupied Building	<u> </u>	None <input checked="" type="checkbox"/>

Additional Spill Details Not Provided Above:

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☐ Corrective Actions Completed (documentation attached)

☒ Work proceeding under an approved Form 27

Form 27 Remediation Project No: 8803

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Blake Ford

Title: Environmental Specialist Date: 08/19/2014 Email: blake.ford@encana.com

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

400667792	FORM 19 SUBMITTED
-----------	-------------------

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

#Error		
--------	--	--

Total: 0 comment(s)