

**Valley Farms L 41A-14-06-92**

<b>Date</b>	<b>Time</b>	<b>Duration/Hr</b>	<b>PSI/GAL</b>	<b>Action</b>
Tue 12/9/2014	0:40	-		Bump Plug - Trace Spacer To Surface
Tue 12/9/2014	4:40	4	0	Pressure Check
Tue 12/9/2014	6:40	6	0	Pressure Check
Tue 12/9/2014	12:40	12	0	Pressure Check
Wed 12/10/2014	0:40	24	0	Pressure Check
Thu 12/11/2014	0:40	48	0	Pressure Check
Fri 12/12/2014	0:40	72	0	Pressure Check
Sat 12/13/2014	6:00	96	0	Pressure Check
Sun 12/14/2014	6:00	120	0	Pressure Check
Mon 12/15/2014	6:00	144	0	Pressure Check
Tue 12/16/2014	6:00	168	0	Pressure Check
Wed 12/17/2014	6:00	192	0	Pressure Check
Thu 12/18/2014	6:00	216	0	Pressure Check
Fri 12/19/2014	6:00	240	0	Pressure Check
Sat 12/20/2014	6:00	264	0	Pressure Check
Sun 12/21/2014	6:00	288	0	Pressure Check
Mon 12/22/2014	6:00	312	0	Pressure Check
Tue 12/23/2014	6:00	336	0	Pressure Check
Wed 12/24/2014	6:00	360	0	Pressure Check
Thu 12/25/2014	6:00	384	0	Pressure Check
Fri 12/26/2014	6:00	408	0	Pressure Check
Sat 12/27/2014	6:00	432	0	Pressure Check
Sun 12/28/2014	6:00	456	0	Pressure Check
Mon 12/29/2014	6:00	480	0	Pressure Check
Tue 12/30/2014	6:00	504	0	Pressure Check
Wed 12/31/2014	6:00	528	0	Pressure Check
Thu 1/1/2015	6:00	552	0	Pressure Check
Fri 1/2/2015	6:00	576	0	Pressure Check
Sat 1/3/2015	6:00	600	0	Pressure Check
Sun 1/4/2015	6:00	624	0	Pressure Check
Mon 1/5/2015	6:00	648	0	Pressure Check
Tue 1/6/2015	6:00	672	0	Pressure Check
Wed 1/7/2015	6:00	696	0	Pressure Check
Thu 1/8/2015	6:00	720	0	Pressure Check
Fri 1/9/2015	6:00	744	0	Pressure Check
Sat 1/10/2015	6:00	768	0	Pressure Check
Sun 1/11/2015	6:00	792	0	Pressure Check
Mon 1/12/2015	6:00	816	0	Pressure Check
Tue 1/13/2015	6:00	840	0	Pressure Check
Sun 1/18/2015	10:11	970	40	Pressure Check
Fri 1/23/2015	16:30	1096	20	Pressure Check