



Photo 1. View of well pad from northeastern corner facing center. A large portion of the well pad does not appear necessary for operations.



Photo 2. View of well pad from southeastern corner facing center. A large portion of the well pad does not appear necessary for operations.



Photo 3. View of narrow, weedy vegetation band on eastern edge of well pad facing southward.



Photo 4. View of weedy, narrow vegetation band on northern edge of project area from northeastern corner facing westward.



Photo 5. View of weedy vegetation band in western portion of project area from northwestern corner facing southward.



Photo 6. View of Russian thistle (*Salsola tragus*) and kochia (*Kochia scoparia*) debris in southern portion of project area.