

Caerus Piceance LLC

Puckett 24D

Location # 335463

Tank battery: Staining around hatches and down sides of tanks.



Housekeeping of tank battery

Condensate spilled inside of containment.



200 bbl tank stained with product.



Unused bolt holes not sealed



Unused bolt holes not sealed.



Bolt together berm with no liner and
no seals a joints.



Day lighting in corner of berm where connected to adjacent berm for 400 bbl tank.

06/20/2014



01/27/2015



Secondary containment full of fluid.



Secondary containment full of fluid.

