

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:

02/03/2015

Document Number:

675100959

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 231811 | 315962 | GRANAHAN, KYLE | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 10027Name of Operator: C & J FIELD SERVICESAddress: 3650 COUNTY RD #2City: RANGELY State: CO Zip: 81648

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|--------------|---------------------------|-----------------|
| | 970-675-5300 | candjfield@centurytel.net | all inspections |
| Thompson, Bud | | BLThomps@BLM.gov | |

Compliance Summary:QtrQtr: SENW Sec: 4 Twp: 2N Range: 103W**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 231811 | WELL | PR | 07/01/2013 | OW | 103-09482 | ADAM 1A | SI | <input checked="" type="checkbox"/> |

Equipment:**Location Inventory**

| | | | |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Signs/Marker: | | | | |
|----------------------|------------------------------|--|---------------------------------------|-------------------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| BATTERY | ACTION REQUIRED | Missing nearest public access road, see photo A1 | Install sign to comply with rule 210. | 03/06/2015 |
| WELLHEAD | SATISFACTORY | | | |
| TANK LABELS/PLACARDS | SATISFACTORY | | | |

Inspector Name: GRANAHAH, KYLE

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: 970-629-5161

Corrective Action: _____

Good Housekeeping:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|--------|------------------------------|--|---|------------|
| DEBRIS | ACTION REQUIRED | Old tank steps/platform laying on location, see photo A2 | Remove from location or install on tank | 03/06/2015 |

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?**Fencing/:**

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|-----------|------------------------------|---------|-------------------|---------|
| PUMP JACK | SATISFACTORY | | | |

Equipment:

| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|--------------------|---|------------------------------|---------|-------------------|---------|
| Deadman # & Marked | 4 | SATISFACTORY | | | |
| Pump Jack | 1 | SATISFACTORY | | | |

Facilities:☐ New Tank

Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|-----------|---|----------|-----------|-----------------------|
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | 40.173920,-108.965260 |

S/A/V: SATISFACTORY

Comment: _____

Corrective Action: _____

Corrective Date: _____

Paint

| Condition | Adequate |
|-----------|----------|
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| Corrective Action | Corrective Date |
|-------------------|-----------------|
| Comment | |

Venting:

| Yes/No | Comment |
|--------|---------|
| NO | |

| | | | | |
|-----------------|------------------------------|---------|-------------------|---------|
| Flaring: | | | | |
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 231811

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/A/V: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/A/V: _____ Comment: _____

CA: _____ Date: _____

Stormwater:

Comment: _____

Staking:**On Site Inspection (305):**Surface Owner Contact Information:Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 231811 Type: WELL API Number: 103-09482 Status: PR Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

S/A/V: SATISFACTORY CA Date: _____

CA: _____

Comment: Production records indicate well last produced in Sep. '14

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Fail CM Tank stairs/landing on location

CA Remove or install

CA Date 03/06/2015

Waste Material Onsite? Pass CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____

CA Date _____

Guy line anchors removed? _____ CM _____

CA _____

CA Date _____

Guy line anchors marked? Pass CM _____

CA _____

CA Date _____

1003b. Area no longer in use? Pass

Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass

Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass

Segregated soils have been replaced? _____

Inspector Name: GRANAHAN, KYLE

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____ In Process _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | | | | | |
| Seeding | Pass | | | | | |

S/A/V: SATISFACTOR _____ Corrective Date: _____

Y

Comment: **Snow cover prevented a full evaluation of stormwater BMP's – no evidence of soil migration at time of inspection.**

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 675100960 | A1 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3545233 |
| 675100961 | A2 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3545234 |

ACTION REQUIRED

ANY ACTION REQUIRED items listed on this report indicate that the oil and gas facility or the oil and gas operations listed on the report may be in violation of the rules and regulations of the Colorado Oil and Conservation Commission (“COGCC”) and corrective action is required.

There is reasonable cause to believe that a violation of the Oil and Gas Conservation Act, or of any rule, regulation, or order of the Commission, or of any permit issued by the Commission, has occurred. The Operator’s compliance with this Inspection Report is required to resolve these alleged violations. This document requires the Operator to timely respond to the COGCC and to comply with directives as listed by the **Corrective Action Deadline Date**. Failure to do so will result in the issuance of a Notice of Alleged Violation and initiation of enforcement proceedings in which COGCC will seek monetary penalties for the alleged violations pursuant to § 34-60-121, C.R.S. and Rule 523, COGCC Rules of Practice and Procedure, 2 CCR 404-1. (Please note that the COGCC's penalty authority was recently increased to a maximum of \$15,000 per day and penalties are no longer capped at a maximum of \$10,000 per violation.)