

WPX Energy

GM14-35 Pad

Location # 334773

Erosion rills of cut slope behind wells



Erosion rills of cut slope behind separators and stacking of sediment.



Erosion rills of cut slope wall being used for back wall of tank berm.



No label on tank



Ditches need maintained

