

WPX Energy

GM 13-33 Pad

Location # 323902

No wells signs. Stains and debris at wells.



Stain and debris at wells



Drum in berm with torn liner.



Storage of equipment and supplies.



No label on tank



Incomplete berm and black fluids in cuttings.



Road shoulders cover by sediment from blading road.

