



photo 1: Center of the location facing north.



photo 2: Center of the location facing west.



photo 3: Center of the location facing south.



photo 4: Center of the location facing east.



photo 5: Weed growth (Russian thistle) throughout the location.



photo 6: East side of the location facing west towards the location.



photo 7: Barb wire found at the north side of the location.



photo 8: Facing south, surrounding vegetation around the location.