

South Shale Ridge 1-14H

Inspection# 675201243

Updated sign from previous inspection.



Weeds in tank containment.

2/16/15



Erosion and rilling on North
side of location.

2/16/15



Erosion and rilling on North
side of location.

12/03/14



Erosion and rilling on North
side of location.

12/03/14



Erosion and rilling on North
side of location.

2/16/15

