

Caerus Piceance LLC

Location # 335793

CHEVERON 13-17D

Ditch full of sediment



Ditch full of sediment



Unstable cut slope washing sediment onto location.



Ruts, rills, ditch washing, soft cut slope



Ruts, rills, ditch washing, soft cut slope

