

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:
02/27/2015Document Number:
673801824Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	435070	435070	Gomez, Jason	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc.djinspections@encana.com	Group email
Kulmann, Dave		dave.kulmann@state.co.us	

Compliance Summary:QtrQtr: SWNW Sec: 19 Twp: 3N Range: 68W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/11/2014	668302424			SATISFACTORY			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
435063	WELL	PR	01/09/2015	LO	123-38442	Bohrer 2I-19H-E368	PR	<input checked="" type="checkbox"/>
435064	WELL	PR	01/09/2015	LO	123-38443	Bohrer 2G-19H-E368	PR	<input checked="" type="checkbox"/>
435065	WELL	PR	01/09/2015	LO	123-38444	Bohrer 2B-19H-E368	PR	<input checked="" type="checkbox"/>
435066	WELL	PR	01/09/2015	LO	123-38445	Bohrer 2E-19H-E368	PR	<input checked="" type="checkbox"/>
435067	WELL	DG	08/05/2014	LO	123-38446	Bohrer 2A-19H-E368	DG	<input checked="" type="checkbox"/>
435068	WELL	PR	01/09/2015	LO	123-38447	Bohrer 2F-19H-E368	PR	<input checked="" type="checkbox"/>
435069	WELL	PR	01/09/2015	LO	123-38448	Bohrer 2C-19H-E368	PR	<input checked="" type="checkbox"/>
435071	WELL	PR	01/09/2015	LO	123-38449	Bohrer 2H-19H-E368	PR	<input checked="" type="checkbox"/>
435072	WELL	PR	01/09/2015	LO	123-38450	Bohrer 2D-19H-E368	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Inspector Name: Gomez, Jason

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>9</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>5</u>	Separators: <u>9</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>13</u>	Oil Tanks: <u>15</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment
--------	---------

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
------	------------------------------	---------	-------------------	---------

Predrill

Location ID: 435070

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 435063 Type: WELL API Number: 123-38442 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 435064 Type: WELL API Number: 123-38443 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 435065 Type: WELL API Number: 123-38444 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 435066 Type: WELL API Number: 123-38445 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 435067 Type: WELL API Number: 123-38446 Status: DG Insp. Status: DG

Producing Well

Comment: PR

Complaint

Comment: Complaint #: 200426023

Field Inspector Assigned: Gomez, Jason

Complaint Received:

Date: 2-27-2015; Time (Military):

Contacted by Inspector:

Date: Time (Military):

Well Number: 05-Choose an item.-Click here to enter text. Location #: 435070

Inspection Document #: 67380 1824

Complainant: Sarah Sharp Stark Phone: 303-485-6414

Address: 161 Hensen Dr Longmont

Nature of complaint: Noise

Field Inspector Actions:

On 2-27-2015, I went back to the Bohrer location to attempt to perform a sound study at the location, Encana had completed the repair with the rig on location. I observed that Encana adjusted the lights on location by moving the lights from the NW end of the location to the south end of the location. The adjustable lighting on location was pointed toward the ground and toward the floor of the rig. Due to the 20 degree temperature I was unable to perform a sound study on location. I again attempted to contact the complainant at her residence and by phone. See attached photos.

Facility ID: 435068 Type: WELL API Number: 123-38447 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 435069 Type: WELL API Number: 123-38448 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 435071 Type: WELL API Number: 123-38449 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 435072 Type: WELL API Number: 123-38450 Status: PR Insp. Status: PR

Workover

Comment:

Environmental

Inspector Name: Gomez, Jason

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: DRY LAND

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Inspector Name: Gomez, Jason

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: DRY LAND, RESIDENTIAL

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673801890	Complainants View	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3570623
673801891	View from Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3570624
673801892	Lights on placement 2-26-2015	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3570625
673801893	Light placement 2-27-2015	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3570626
673801894	No Grounding on tanks	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3570627