



Photo 1. Birdseye view of revegetation in northeastern portion of interim reclamation area that appears to be dominated by cheatgrass (*Bromus tectorum*).





Photo 2. View of northwestern portion of interim reclamation area that appears to be largely dominated by cheatgrass. From northern corner facing southwestward.





Photo 3. View of dense kochia population in northwestern portion of project area.





Photo 4. View of progressing revegetation within southwestern portion of project area from southern corner facing northwestward.





Photo 5. View of rill erosion within northeastern portion of project area.





Photo 6. View of rill erosion in northwestern portion of project area.





Photo 7. View of hole where it appears stormwater flows have eroded the well pad and begin to flow beneath the ground.