



STATE OF
COLORADO

EnviroScan - DNR, OGCC <dnr_ogcc.enviroscan@state.co.us>

Fwd: 2014 Love Ranch 8 E&P Waste Facility Annual Report Facility # 149012

1 message

Fischer - DNR, Alex <alex.fischer@state.co.us>

Wed, Mar 25, 2015 at 10:09 AM

To: OGCC EnviroScan - DNR <dnr_ogcc.enviroscan@state.co.us>

Please upload the attached and email with the following information:

Unique identifier (REM/Spill/NOAV #, etc.): Facility # 149012

Document number (leave blank if one needs to be assigned):

Date received: March 16, 2015

Is data entry needed (Y/N): N

Notes: Please label the attachment "REVISED 2014 Love Ranch 8 E&P Waste Facility Annual Report"

Thanks!

--

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado



P 303.894.2100 x5138 | F 303.894.2109

1120 Lincoln Street, Suite 801, Denver, CO 80203

| alex.fischer@state.co.us www.colorado.gov/cogcc

----- Forwarded message -----

From: **Dooling, Jessica** <Jessica_Dooling@xtoenergy.com>

Date: Mon, Mar 16, 2015 at 12:33 PM

Subject: RE: 2014 Love Ranch 8 E&P Waste Facility Annual Report Facility # 149012

To: "Fischer - DNR, Alex" <alex.fischer@state.co.us>

Cc: "Spencer - DNR, Stan" <stan.spencer@state.co.us>, "Littrell, Kyle" <Kyle_Littrell@xtoenergy.com>, "Bowers, David" <David_Bowers@xtoenergy.com>

Hi Alex,

In response to your comments:

- The five (5) piezometer locations are included in the Annual Dam Report to the State Engineers Office included in the attached revised annual report and will be included in future submittals. The piezometers were installed as a part of the pond installation as required by the State Engineers office; they act as an early detection system in the event of a pond integrity issue.
- The State Engineers office changed the Dam Inspection frequency during their 2014 inspection, the required inspection frequency is now quarterly. The rodent and erosion issues noted are ongoing in nature and corrected when identified. Inspection reports are in Annual Dam Report to the State Engineers Office included in the attached revised annual report and will be included in future submittals.
- XTO submits an annual report to the State Engineers office, see attached. The annual report includes the current attachments to the Love Ranch 8 E&P Waste Facility Annual Report Facility # 149012. In future submittals to COGCC the Annual Report to the State Engineers office will be attached in lieu of currently provided attachments.

Please contact me with any comments or question and thanks for your help.

Jes

From: Fischer - DNR, Alex [mailto:alex.fischer@state.co.us]

Sent: Tuesday, March 10, 2015 8:13 AM

To: Dooling, Jessica

Subject: Re: 2014 Love Ranch 8 E&P Waste Facility Annual Report Facility # 149012

Jessica,

Thanks for providing the 2014 Annual Report. Please clarify the following:

- There are five (5) piezometers that were installed near or around the Facility please indicate on a diagram the locations of these monitoring points. These monitoring points appear to be dry with the exception of a "trace" < 0.01 - 0.09 feet of moisture. Are these monitoring points requirements of the State Engineers Office or the COGCC? Should these monitoring points be properly abandoned? as they may be potential conduits for contaminants to enter into the subsurface.
- Attachment C provides monthly "Dam Inspections" with similar notes about rodent holes and erosion issues that appear on all of the monthly inspections. These issues shall be addressed upon discovery and reinspected after they have been addressed. These inspections shall be documented as part of the annual report.
- Does XTO provide monthly or annual reports to the State Engineers Office? If so, please include those reports in the annual submittal to the COGCC.

Thanks

Alex

On Tue, Mar 10, 2015 at 7:09 AM, Dooling, Jessica <Jessica_Dooling@xtoenergy.com> wrote:

Hi Alex,

Attached is the 2014 Love Ranch 8 E&P Waste Facility Annual Report (Facility # 149012) for your review. Hard copy of the report has been sent to your attention at the Denver COGCC office. Please contact me with any comments or questions.

Jes

Jessica Dooling

Piceance EHS Supervisor

Jessica_dooling@xtoenergy.com

970-675-4122 Office

970-769-6048 Cell

XTO Energy

21459 CR 5, Rifle, CO 81650

--

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado



P 303.894.2100 x5138 | F 303.894.2109

1120 Lincoln Street, Suite 801, Denver, CO 80203

| alex.fischer@state.co.us www.colorado.gov/cogcc

--

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado



P [303.894.2100](tel:303.894.2100) x5138 | F [303.894.2109](tel:303.894.2109)

1120 Lincoln Street, Suite 801, Denver, CO 80203

| alex.fischer@state.co.us www.colorado.gov/cogcc



20150316 Love Ranch 8 E&P Waste Annual Report 2014.pdf
1044K