

Reference Area Photographs

Inspection Conducted on Month xx, 2014

**Caerus Piceance LLC
Island Ranch 13-796 pad
Location ID #436810**

Island Ranch 13-796 pad



Signs with emergency number and Site information



Tanks labeled and bermed. Clean pad. No staining observed, no weeds or junk.

Island Ranch 13-796 pad



Landfarm operation



Landfarm operation and pad. Well heads protected with fence.

Island Ranch 13-796 pad



Canal on the perimeter of the land farmed cells.

