

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:
04/01/2015Document Number:
675201396Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection <input type="checkbox"/>
	334662	334662	CONKLIN, CURTIS	2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	All Inspections

Compliance Summary:QtrQtr: SENE Sec: 25 Twp: 7S Range: 96W**Inspector Comment:**Follow up to inspection Doc#663800765 Issues have been resolved from previous inspection**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
111951	PIT		09/23/1999		-	FEDERAL H-25-7-96-W		<input type="checkbox"/>
210546	WELL	PA	06/22/2005	GW	045-06302	FEDERAL H-25-7-96-W	PA	<input type="checkbox"/>
275163	WELL	AL	11/06/2009	LO	045-13472	FEDERAL (PH25) 25-9	AL	<input type="checkbox"/>
275164	WELL	PR	07/19/2006	GW	045-13471	FEDERAL (PH25) 25-2	PR	<input checked="" type="checkbox"/>
275165	WELL	AL	11/03/2009	LO	045-13470	FEDERAL 25-7(PH25)	AL	<input type="checkbox"/>
275166	WELL	AL	11/06/2009	LO	045-13469	FEDERAL 25-1 (PH25)	AL	<input type="checkbox"/>
279218	WELL	AL	11/20/2009	LO	045-11015	FEDERAL 25-8 (PH25)	AL	<input type="checkbox"/>
415630	WELL	PR	08/04/2011	GW	045-19121	Federal 25-8 (PH25)	PR	<input checked="" type="checkbox"/>
415633	WELL	PR	10/10/2011	GW	045-19122	Federal 25-2BB (PH25)	PR	<input checked="" type="checkbox"/>
415635	WELL	PR	05/07/2011	GW	045-19123	Federal 25-9 (PH25)	PR	<input checked="" type="checkbox"/>
415643	WELL	PR	10/10/2011	GW	045-19124	Federal 25-8BB (PH25)	PR	<input checked="" type="checkbox"/>
415646	WELL	PR	09/16/2011	GW	045-19125	Federal 25-7 (PH25)	PR	<input checked="" type="checkbox"/>

Inspector Name: CONKLIN, CURTIS

415648	WELL	PR	09/10/2011	GW	045-19126	Federal 25-7BB (PH25)	PR	<input checked="" type="checkbox"/>
415650	WELL	PR	08/04/2011	GW	045-19127	Federal 25-1BB (PH25)	PR	<input checked="" type="checkbox"/>
415870	WELL	PR	10/10/2011	GW	045-19169	Federal 25-1 (PH25)	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>9</u>	Production Pits: _____
Condensate Tanks: <u>4</u>	Water Tanks: _____	Separators: <u>9</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: <u>1</u>
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: <u>1</u>	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: 1-800-791-7691

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	Panels		

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Plunger Lift	9	SATISFACTORY			
Bird Protectors	5	SATISFACTORY			
Horizontal Heated Separator	9	SATISFACTORY			
Ancillary equipment	1	SATISFACTORY	Chem unit w/ containment		
Gas Meter Run	1	SATISFACTORY			

Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	1	300 BBLS	STEEL AST	,	
S/A/V:	SATISFACTORY		Comment: No Airs ID		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Corrective Action				Corrective Date	
Comment				Same	
Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	2	500 BBLS	STEEL AST	,	
S/A/V:	SATISFACTORY		Comment:		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
<u>Venting:</u>					
Yes/No		Comment			
NO					
<u>Flaring:</u>					
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date	

Predrill

Location ID: 334662

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 275164 Type: WELL API Number: 045-13471 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 415630 Type: WELL API Number: 045-19121 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 415633 Type: WELL API Number: 045-19122 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 415635 Type: WELL API Number: 045-19123 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 415643 Type: WELL API Number: 045-19124 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 415646 Type: WELL API Number: 045-19125 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 415648 Type: WELL API Number: 045-19126 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 415650 Type: WELL API Number: 045-19127 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 415870 Type: WELL API Number: 045-19169 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Inspector Name: CONKLIN, CURTIS

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Inspector Name: CONKLIN, CURTIS

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
Retention Ponds	Pass	Gravel	Pass			
Compaction	Pass	Culverts	Pass			
Gravel	Pass	Ditches	Pass			
Berms	Pass	Compaction	Pass			

S/A/V: SATISFACTOR
Y Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675201396	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3582416