Cover Data

Date: 9/25/14 Inspected By: G. HELGELAND

Location: API # 075-09336 / WINSLOW RESOURCES

Transect #/disturbed/Ref	DISTURBED				UNDISTURBED		
Transect Orientation and first photo, degrees	40.84201 N 103.38957 W				40.84207N 103.38913W		
Photo Midpoint (2)	E, W				E, W		
End transect	40.84228 N		103.38966W		40.84229 N		103.38911 W
Photo other							
Photo other							
Aspect/Slope	FLAT				FLAT		
	1st Hit	2nd	1st Hit	2nd	1st Hit	2nd	1st Hit
Litter					4		
Bare Soil	31				6		
Rock							
Total Weeds							
Total Desirable Species	19				40		
80% Check	38%	=	48% of →		80%	=	FAIL
Species							
BUFFALO GRASS	14				27		
WHEAT GRASS	5				12		
CACTUS	—				1		