
gyrodata
DIRECTIONAL SURVEY
RECORD OF SURVEY
RADIUS OF CURVATURE METHOD
Survey Date: 08 JUL 2014
Job No: 14AK0001
Well: 1H
Field: Kuparuk River Unit
Location: North Slope, Alaska
Rig: Doyon 141
Gyro: 1000' GYRO
Surveyed: 0' TO 10,000'
Declination: 0.00 E
Convergence: 0.00
Grid Correction: 0.00
Total Correction: 0.00
Vertical Section Plane: 0.00
Vertical Section Origin: 0.00 N, 0.00 E
Horizontal Coordinates: Referenced to Well Head
Vertical Depths: Referenced to Rotary Table
Rotary Table Elevation: 0.00 ft above Mean Sea Level
Mean Sea Level Elevation: 0.00 ft above Mud Line
Survey Depth: 0.00 ft below Mud Line
Survey Depth: 0.00 ft below Rotary Table
Survey Depth: 0.00 ft below Kelly Bushing
Survey Depth: 0.00 ft below Casing Flange
Survey Depth: 0.00 ft below Tubing Head
Survey Depth: 0.00 ft below Ground Level