

CEMENT JOB REPORT



CUSTOMER BAYSWATER EXPLORATION &		DATE 08-AUG-14	F.R. # 10011089115		SERV. SUPV. VITALIJS A NEVERDASOV		
LEASE & WELL NAME KAISER #A-10HN - API 05123396040000		LOCATION 10-6N-65W		COUNTY-PARISH-BLOCK Weld Colorado			
DISTRICT Brighton		DRILLING CONTRACTOR RIG # Frontier 8		TYPE OF JOB Surface			
SIZE & TYPE OF PLUGS	LIST-CSG-HARDWARE	MECHANICAL BARRIERS	MD	TVD	HANGER TYPES	MD TVD	
9-5/8" Top Cem Plug, Nitrile cvr, Phe	Float Shoe 9-5/8 - 8rd	NONE	0	0	NONE	0 0	
	Alum Baffle Plate, Slip On, 9-5/8						
	Centralizer, with Pins, 9-5/8 in						
	Cement Basket, Slip On, 9-5/8 in						
MATERIALS FURNISHED BY BJ		LAB REPORT NO.	PHYSICAL SLURRY PROPERTIES				
Fresh Water	N/A	0	8.34	0	0	00:00	
Type III Cement + Adds	N/A	250	14.5	1.41	6.81	00:00	
Fresh Water	N/A	0	8.34	0	0	00:00	
Available Mix Water 700 Bbl.		Available Displ. Fluid 500 Bbl.		TOTAL		122.85 40.53	
HOLE		TBG-CSG-D.P.				COLLAR DEPTHS	
SIZE	% EXCESS	DEPTH	ID	OD	WGT.	TYPE	MD TVD GRADE
12.25	30	758	8.835	9.625	36	CSG	748 748 J-55
LAST CASING		PKR-CMT RET-BR PL-LINER		PERF. DEPTH		TOP CONN WELL FLUID	
ID	OD	WGT	TYPE	MD	TVD	BRAND & TYPE	DEPTH TOP BTM
						NO PACKER	0 9.625 8RND FRESH WATER 8.4
DISPL. VOLUME		DISPL. FLUID		CAL. PSI	CAL. MAX PSI	OP. MAX	MAX TBG PSI MAX CSG PSI
VOLUME	UOM	TYPE	WGT.	BUMP PLUG	TO REV.	SQ. PSI	RATED Operator RATED Operator
54.3	BBLS	Fresh Water	8.34	228	0	0	0 0 2816 1000 RIG TANK
Circulation Prior to Job							
Circulated Well: Rig <input checked="" type="checkbox"/> BJ <input type="checkbox"/>				Circulation Time: 1		Circulation Rate: 5 BPM	
Mud Density In: 8.4 LBS/GAL Mud Density Out: 8.4 LBS/GAL				PV & YP Mud In: 0		PV & YP Mud Out: 0	
Gas Present: NO <input checked="" type="checkbox"/> YES <input type="checkbox"/> Units:				Solids Present at End of Circulation: NO <input checked="" type="checkbox"/> YES <input type="checkbox"/>			
Displacement And Mud Removal							
Displaced By: Rig <input type="checkbox"/> BJ <input checked="" type="checkbox"/>				Amount Bled Back After Job: 1 BBLS			
Returns During Job: <input type="checkbox"/> NONE <input type="checkbox"/> PARTIAL <input checked="" type="checkbox"/> FULL				Method Used to Verify Returns: VISUAL			
Cement Returns at Surface: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				Were Returns Planned at Surface: <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES			
Pipe Movement: <input type="checkbox"/> ROTATION <input type="checkbox"/> RECIPROCATION <input type="checkbox"/> NONE <input type="checkbox"/> UNABLE DUE TO STUCK PIPE							
Centralizers: <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES				Quantity: 8		Type: <input type="checkbox"/> BOW <input type="checkbox"/> RIGID	
Job Pumped Through: <input type="checkbox"/> CHOKE MANIFOLD <input type="checkbox"/> SQUEEZE MANIFOLD <input type="checkbox"/> MANIFOLD <input type="checkbox"/> NO MANIFOLD							
Plugs							
Number of Attempts by BJ: 0 Competition: 0				Wiper Balls Used: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES Quantity:			
Plug Catcher Used: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES				Parabow Used: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES			
Was There a Bottom: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES				Top of Plug: 0 FT Bottom of Plug: 0 FT			
Squeezes (Update Original Treatment Report for Primary Job)							
BLOCK SQUEEZE <input type="checkbox"/> SHOE SQUEEZE <input type="checkbox"/> TOP OF LINER SQUEEZE <input type="checkbox"/> PLANNED <input type="checkbox"/> UNPLANNED <input type="checkbox"/>							
Liner Packer: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES				Bond Log: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES		PSI Applied: 0 Fluid Weight: 0 LBS/GAL	
Casing Test (Update Original Treatment Report for Primary Job)							
Casing Test Pressure: 0 PSI With 0 LBS/GAL Mud				Time Held: 00 Hours 00 Minutes			
EXPLANATION: TROUBLE SETTING TOOL, RUNNING CSG, ETC. PRIOR TO CEMENTING NONE							

CEMENT JOB REPORT



Shoe Test (Update Original Treatment Report for Primary Job)

Depth Drilled out of Shoe: 0 FT Target EMW: 0 LBS/GAL Actual EMW: 0 LBS/GAL
 Number of Times Tests Conducted: 0 Mud Weight When Test was Conducted: 0 LBS/GAL

Problems Before Job (I.E. Running Casing, Circulating Well, ETC)
 NONE

Problems During Job (I.E. Lost Returns, Equipment Failure, Bulk Delivery, Foaming, ETC)
 NONE

Problems After Job (I.E. Gas at Surface, Float Equipment Failed, ETC)
 NONE

PRESSURE/RATE DETAIL						EXPLANATION	
TIME HR:MIN.	PRESSURE - PSI		RATE BPM	Bbl. FLUID PUMPED	FLUID TYPE	SAFETY MEETING: BJ CREW <input checked="" type="checkbox"/> CO. REP. <input checked="" type="checkbox"/>	
	PIPE	ANNULUS				TEST LINES 2520 PSI	
						CIRCULATING WELL - RIG <input checked="" type="checkbox"/> BJ <input type="checkbox"/>	
22:05	0	0	0	0	N/A	CREW STAY ON LOCATION AFTER PREVIOUS JOB	
04:30	0	0	0	0	N/A	CALLED YARD/ CUSTOMER REQUESTED CREW @ 8:00	
11:32	0	0	0	0	N/A	SPOT TRUCKS/ 3 JOINTS OF CASING IS LEFT TO RUN	
11:38	0	0	0	0	N/A	PRE RIG UP SAFETY MEETING	
12:35	0	0	0	0	N/A	PRE JOB SAFETY MEETING	
13:02	21	0	1.3	2	H2O	LOAD LINE	
13:04	2520	0	.4	.1	H2O	PRESSURE TEST	
13:07	136	0	5.2	10	H2O	FRESH WATER	
13:09	138	0	5.2	10	H2O	DYE SPACER	
13:14	102	0	2.9	63	CMT	BATCHWEIGH/PUMP 250 SX OF CEMENT @ 14.5 PPG	
13:39	0	0	0	0	N/A	SHUT DOWN/ DROP PLUG	
13:44	346	0	5.2	40	H2O	DISPLACEMENT	
13:52	371	0	2	14	H2O	SLOW RATE	
13:59	984	0	0	54	H2O	BUMP PLUG	
14:04	0	0	0	0	N/A	CHECK FLOATS/ FLOATS HELD	
14:10	0	0	0	0	N/A	RIG DOWN SAFETY MEETING	
BUMPED PLUG <input type="checkbox"/> Y <input checked="" type="checkbox"/> N	PSI TO BUMP PLUG 371	TEST FLOAT EQUIP. <input type="checkbox"/> Y <input checked="" type="checkbox"/> N	BBL.CMT RETURNS/ REVERSED 15	TOTAL BBL. PUMPED 137	PSI LEFT ON CSG 0	SPOT TOP OUT CEMENT Y <input type="checkbox"/> N <input checked="" type="checkbox"/>	Service Supervisor Signature:

