

WPX Energy

Location # 335916

TR 12-25-597 Pad

Berm of stained sand behind wells.



Stained sand and storm water in berm.



Hole in berm liner.



Liner slipping off berm wall.



Liner debris on location.



Unstable Cut slope.

