

Bosely SG 24-22

Inspection# 675200975

Sediment run on at NE corner of
location behind tanks.



Sediment run on along access road.
(39.41645/-108.09816)



Sediment run on along access
road.

(39.41645/-108.09816)



Erosion along access road.

(39.41645/-108.09816)



Sediment run on along access
road.

