



**State of Colorado**  
**Oil and Gas Conservation Commission**  
DEPARTMENT OF NATURAL RESOURCES

RECEIVED  
FEB -2 98  
00000

**SUNDRY NOTICE**

Submit original plus one copy. This form is to be used for general, technical and environmental sundry information. For proposed or completed operations, describe in full on Technical Information Page (back of this form).

ET	OE	PR	ES
----	----	----	----

1. OGCC Operator Number: <b>06495</b>	4. Contact Name & Phone
2. Name of Operator: <b>BARRETT RESOURCES CORP.</b>	<b>Duane Zavadil</b>
3. Address: <b>1515 Arapahoe St., Tower 3, Ste. #1000</b>	No: <b>(303)572-3900</b>
City: <b>Denver</b> State: <b>CO.</b> Zip: <b>80202</b>	Fax: <b>(303) 629-8265</b>

Complete the  
Attachment Checklist

Oper OGCC

5. API Number: <b>05-045-6653</b>	6. OGCC Lease No:
7. Well Name: <b>GV 16-33A</b>	Number:
8. Location (QtrQtr, Sec, Twp, Rng, Meridian): <b>NENW Sec.33, T6S R96W, 6th P.M.</b>	
9. County: <b>Garfield</b>	10. Field Name: <b>Grand Valley</b>
11. Federal, Indian or State Lease Number:	

Survey Plat		
Directional Survey		
Surface Equipment		
Technical Information Page		
Other		

**12. General Notice**

☐ Change well name from \_\_\_\_\_ to \_\_\_\_\_ Effective Date: \_\_\_\_\_

☐ Change of location from \_\_\_\_\_  
Attach new survey plat. to \_\_\_\_\_

☐ Abandoned Location. Is site ready for inspection? ☐ Yes ☐ No Effective Date: \_\_\_\_\_  
Was location ever built? ☐ Yes ☐ No Permit No: \_\_\_\_\_

☐ Well first shut in or temporarily abandoned \_\_\_\_\_ Notice of continued shut-in status.  
Has production equipment been removed from Site? ☐ Yes ☐ No  
MIT required if shut in longer than two years. Date of last MIT: \_\_\_\_\_

☐ Well resumed production on \_\_\_\_\_

☐ Request for Confidential Status (6 months).

☐ Final reclamation will commence approximately on \_\_\_\_\_

☐ Final reclamation is completed and site is ready for inspection. Attach technical page describing final reclamation procedures per \_\_\_\_\_

☐ Change of Operator (prior to drilling). Effective Date: \_\_\_\_\_ Plugging bond: ☐ Blanket ☐ Individual

☐ Spud Date \_\_\_\_\_

**13. Technical Engineering/Environmental Notice**

<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Report of Work Done
Approximate Start Date: _____	Date work Completed: <b>January, 1998</b>

Details of work must be described in full on Technical Informtion Page (Page 2 must be submitted).

<input type="checkbox"/> Commingle Zones	<input type="checkbox"/> Request to Vent or Flare	<input type="checkbox"/> E & P Waste Disposal
<input type="checkbox"/> Intent to Recomplete	<input type="checkbox"/> Repair Well	<input type="checkbox"/> Beneficial Reuse of E&P Waste
<input type="checkbox"/> Change Drilling Plans	<input type="checkbox"/> Convert Well to Injection (in an	<input type="checkbox"/> New Pit
<input type="checkbox"/> Reservoir Stimulation	Approved Secondary Project)	<input type="checkbox"/> Landfarming
<input type="checkbox"/> Perforating/Perfs Added	<input type="checkbox"/> Additional Source Leases for	<input type="checkbox"/> Status Update/Change of
Gross Interval Changed?	Water Disposal Well	Remediation Plans for Spills and
<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Other: _____	Releases

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: **Duane Zavadil**  
Signed: \_\_\_\_\_ Title: **Envrionmental Manager** Date: **02/02/98**

OGCC Approved: \_\_\_\_\_ Title: \_\_\_\_\_ Date: \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

111576  
entered  
4/99 KD

TECHNICAL INFORMATION PAGE

FOR OGCC USE ONLY

ET	OE	PR	ES
----	----	----	----

1. OGCC Operator Number:	06495	2. API Number:	05-045-6653
3. Name of Operator:	BARRETT RESOURCES CORP.		
4. Well Name:	GV 16-33A	Number:	
5. Location (QtrQtr, Sec, Twp, Rng, Meridian):	NE1/4 Sec.33, T6S R96W, 6th P.M.		

This form is to be completed whenever a Sundry Notice is submitted requiring detailed report of work to be performed or completed. This form shall be transmitted within thirty (30 days of work) completed as a "subsequent" report and must accompany Form 4, Page 1.

6. DESCRIBE PROPOSED OR COMPLETED OPERATIONS

Concrete vaults used for storage of produced water were found to leak when tested.  
Vaults were replaced with an 80 bbl steel water tank. ✓