



photo 1: Well sign, Bruscher 13-5R.



photo 2: Well sign, Bruscher 13-5V. Well name label is faded and peeling off.



photo 3: North side of the location. Unused pipe and metal panels remain on the location.



photo 4: South side of the location. Unused metal pipe and rods remain on the location.



photo 5: Unused equipment at the southwest side of location.



photo 6: Common mullien (list c noxious weed) growing near the equipment.



photo 5: Metal tin debris found at the north side of the location.



photo 5: East side of the location. Erosion channels have formed transporting sediment off the pad.