



05-057-06005
Location # 383806

Oil-Water Spill/Complaint Inspection Form

Location SCN 30-10N-79W

Field MICHIGAN RIVER

Operator PAULEY / HOWDO

County JACKSON

Well Name ALAND #1

API # _____

Person calling in complaint: BLAINE HAMPTON

Date of Occurrence: FEB 15, 1988

Date of complaint: FEB 16, 1988

Phone# : 307-472-0921 (CASPER)

Follow up by phone: Date _____
Contact _____

Follow up by field visit: Date _____
Contact _____

Type of fluid spill/overflow: OIL/WATER MIXTURE

Estimated volume of fluid: 40-60 BBL

Area effected: 30 x 100

Did spill/overflow reach waters of the state? Yes _____ No X

Remedial action: Sundry notice required - Yes X No _____
(Rule 329) How was spill/overflow cleaned up?

Comments: LIVE BREAK WHILE CIRCULATING WELL

Ran 30 x 100 on RR RIGHT-OF-WAY

CLOSEST River - 1/4 mi AWAY MICHIGAN RIVER
CONTAINED

NOTED NEED FOR New Well SIGNS