

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:  
06/10/2015Document Number:  
666801059Overall Inspection:  
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	285877	334666	Murray, Richard	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Compliance Summary:**QtrQtr: SWSW Sec: 1 Twp: 7S Range: 92W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/10/2015	666800740	PR	PR	ACTION REQUIRED			No
08/22/2008	200194090	DG	WO	SATISFACTORY			No
08/25/2007	200122346	CO	PR	SATISFACTORY			No
01/22/2007	200106950	PR	SI	SATISFACTORY	I	Pass	No
10/10/2006	200103323	CO	WO	SATISFACTORY		Pass	No
09/19/2006	200098490	CC	DG	SATISFACTORY	I	Pass	No
09/19/2006	200096438	CC	DG	SATISFACTORY	I	Pass	No

**Inspector Comment:**Action required items noted in previous inspection have been satisfied**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
285781	WELL	PR	01/06/2007	GW	045-12515	JUNIPER 1-13A (M1E)	PR	<input checked="" type="checkbox"/>
285875	WELL	PR	12/27/2006	GW	045-12582	JUNIPER 2-16A (M1E)	PR	<input checked="" type="checkbox"/>
285876	WELL	PR	12/30/2006	GW	045-12581	JUNIPER 2-16 (M1E)	PR	<input checked="" type="checkbox"/>
285877	WELL	PR	12/19/2006	GW	045-12580	JUNIPER 1-13 (M1E)	PR	<input checked="" type="checkbox"/>
296480	WELL	PR	10/23/2008	GW	045-16049	JUNIPER 1-12A (M1E)	PR	<input checked="" type="checkbox"/>
296481	WELL	PR	10/09/2008	GW	045-16050	JUNIPER 2-9(M1E)	PR	<input checked="" type="checkbox"/>

Inspector Name: Murray, Richard

296482	WELL	PR	10/19/2008	GW	045-16051	JUNIPER 1-12(M1E)	PR	<input checked="" type="checkbox"/>
296483	WELL	PR	10/21/2008	GW	045-16052	JUNIPER 12-4A(M1E)	PR	<input checked="" type="checkbox"/>
296484	WELL	PR	10/30/2008	GW	045-16053	JUNIPER 11-1A (M1E)	PR	<input checked="" type="checkbox"/>
296609	WELL	PR	10/19/2008	GW	045-16088	JUNIPER 2-9A (M1E)	SI	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location****Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY	AIRS ID 045-1522-001		

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Equipment:**

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Gas Meter Run	1	SATISFACTORY			
Ancillary equipment	1	SATISFACTORY	Chemical unit at wellhead		
Horizontal Heated Separator	10	SATISFACTORY			
Emission Control Device	1	SATISFACTORY			
Plunger Lift	10	SATISFACTORY			

**Venting:**

Yes/No	Comment
YES	

**Flaring:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 285877

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 285781 Type: WELL API Number: 045-12515 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift, Bradenhead venting into 90bbls flat tank

Facility ID: 285875 Type: WELL API Number: 045-12582 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Facility ID: 285876 Type: WELL API Number: 045-12581 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Inspector Name: Murray, Richard

Facility ID: 285877 Type: WELL API Number: 045-12580 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Facility ID: 296480 Type: WELL API Number: 045-16049 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Facility ID: 296481 Type: WELL API Number: 045-16050 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Facility ID: 296482 Type: WELL API Number: 045-16051 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Facility ID: 296483 Type: WELL API Number: 045-16052 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Facility ID: 296484 Type: WELL API Number: 045-16053 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Facility ID: 296609 Type: WELL API Number: 045-16088 Status: PR Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

S/A/V: SATISFACTORY CA Date: \_\_\_\_\_

CA: \_\_\_\_\_

Comment: \_\_\_\_\_

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Inspector Name: Murray, Richard

Emission Control Burner (ECB): Y

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

### Reclamation - Storm Water - Pit

#### Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? Pass CM CA Date  
Waste Material Onsite? Pass CM CA Date  
Unused or unneeded equipment onsite? Pass CM CA Date  
Pit, cellars, rat holes and other bores closed? CM CA Date  
Guy line anchors removed? Pass CM CA Date  
Guy line anchors marked? Pass CM CA Date

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit?

Cuttings management:

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?

Production areas have been stabilized?

Segregated soils have been replaced?

#### RESTORATION AND REVEGETATION

##### Cropland

Top soil replaced Recontoured Perennial forage re-established

##### Non-Cropland

Top soil replaced Recontoured 80% Revegetation

1003 f. Weeds Noxious weeds?

Comment:

Overall Interim Reclamation

#### Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: Date Final Reclamation Completed:

Final Land Use:

Reminder:

Inspector Name: Murray, Richard

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_  
Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_  
Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_  
Gravel removed \_\_\_\_\_  
Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_  
Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_  
Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_  
Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment:

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Slope Roughening	Pass					
Retention Ponds	Pass					
		Gravel	Pass			
Berms	Pass					
		Culverts	Pass			
Seeding	Pass					
Ditches	Pass					

S/A/V: SATISFACTOR  
Y

Corrective Date: \_\_\_\_\_

Comment:

CA:

**Pits:** ☒ NO SURFACE INDICATION OF PIT