

FORM
5A

Rev
06/12

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400846992

Date Received:

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: <u>5</u>	4. Contact Name: <u>Collin Androus</u>
2. Name of Operator: <u>COLORADO OIL & GAS CONSERVATION</u>	Phone: <u>(303) 894-2100</u>
3. Address: <u>1120 LINCOLN ST SUITE 801</u>	Fax: _____
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80203</u>	Email: <u>collin.androus@state.co.us</u>

5. API Number <u>05-067-08802-00</u>	6. County: <u>LA PLATA</u>
7. Well Name: <u>MONITOR WELL</u>	Well Number: <u>35-6-17-1</u>
8. Location: QtrQtr: <u>SESE</u> Section: <u>17</u> Township: <u>35N</u> Range: <u>6W</u> Meridian: <u>N</u>	
9. Field Name: <u>IGNACIO BLANCO</u> Field Code: <u>38300</u>	

Completed Interval

FORMATION: FRUITLAND COAL-MESAVERDE Status: SHUT IN Treatment Type: _____
Treatment Date: _____ End Date: _____ Date of First Production this formation: _____
Perforations Top: 1572 Bottom: 1584 No. Holes: 12 Hole size: 0.4
Provide a brief summary of the formation treatment: _____ Open Hole: ☐

none.
Upper transducer set at 5 feet below ground surface. Type and Rating is the LT 500 - 300 psia.
Lower transducer set at 1551 feet below ground surface. Type and Rating is the LT 700 - 1000 psia
Perforations 1572 to 1576, and 1582 to 1584. 2 holes per foot. 0.4 in

This formation is commingled with another formation: ☒ Yes ☐ No
Total fluid used in treatment (bbl): _____ Max pressure during treatment (psi): _____
Total gas used in treatment (mcf): _____ Fluid density at initial fracture (lbs/gal): _____
Type of gas used in treatment: _____ Min frac gradient (psi/ft): _____
Total acid used in treatment (bbl): _____ Number of staged intervals: _____
Recycled water used in treatment (bbl): _____ Flowback volume recovered (bbl): _____
Fresh water used in treatment (bbl): _____ Disposition method for flowback: _____
Total proppant used (lbs): _____ Rule 805 green completion techniques were utilized: ☐
Reason why green completion not utilized: _____

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: _____ Hours: _____ Bbl oil: _____ Mcf Gas: _____ Bbl H2O: _____
Calculated 24 hour rate: _____ Bbl oil: _____ Mcf Gas: _____ Bbl H2O: _____ GOR: _____
Test Method: _____ Casing PSI: _____ Tubing PSI: _____ Choke Size: _____
Gas Disposition: _____ Gas Type: _____ Btu Gas: _____ API Gravity Oil: _____
Tubing Size: _____ Tubing Setting Depth: _____ Tbg setting date: _____ Packer Depth: _____
Reason for Non-Production: Monitoring Well
Date formation Abandoned: _____ Squeeze: ☐ Yes ☐ No If yes, number of sacks cmt _____
** Bridge Plug Depth: _____ ** Sacks cement on top: _____ ** Wireline and Cement Job Summary must be attached.

Comment:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Collin Androus
Title: Environmental Scientist Date: _____ Email: collin.androus@state.co.us
:

Attachment Check List

Att Doc Num **Name**

Total Attach: 0 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	Upper transducer set at 5 feet below ground surface. Type and Rating is the LT 500 - 300 psia. Lower transducer set at 1551 feet below ground surface. Type and Rating is the LT 700 - 1000 psia Perforations 1572 to 1576, and 1582 to 1584. 2 holes per foot. 0.4 in	6/15/2015 11:35:57 AM

Total: 1 comment(s)