

FORM  
5

Rev  
09/14

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400718879

Date Received:

10/28/2014

DRILLING COMPLETION REPORT

Per Rule 308A, this form and all required attachments shall be submitted after completing the drilling operations to drill, sidetrack, or deepen a wellbore and after changing the casing and cement configuration of a wellbore. If any attempt has been made to test, complete, or produce the well, the operator shall also submit a Form 5A (Completed Interval Report) per Rule 308B. If the well has been plugged, the operator shall also submit a Form 6 (Well Abandonment Report) per Rule 311.

Completion Type  Final completion  Preliminary completion

OGCC Operator Number: 100322 Contact Name: Kathleen Mills  
Name of Operator: NOBLE ENERGY INC Phone: (720) 587-2226  
Address: 1625 BROADWAY STE 2200 Fax: (303) 228-4286  
City: DENVER State: CO Zip: 80202

API Number 05-123-38096-00 County: WELD  
Well Name: EAGLE Well Number: E14-65-1HN  
Location: QtrQtr: NWSW Section: 14 Township: 6N Range: 65W Meridian: 6  
Footage at surface: Distance: 2350 feet Direction: FSL Distance: 364 feet Direction: FWL  
As Drilled Latitude: 40.485241 As Drilled Longitude: -104.638798

GPS Data:  
Date of Measurement: 04/10/2014 PDOP Reading: 2.1 GPS Instrument Operator's Name: RILEY JONSSON

\*\* If directional footage at Top of Prod. Zone Dist.: 2350 feet Direction: FSL Dist.: 1161 feet Direction: FWL  
Sec: 14 Twp: 6N Rng: 65W

\*\* If directional footage at Bottom Hole Dist.: 2317 feet Direction: FSL Dist.: 784 feet Direction: FWL  
Sec: 13 Twp: 6N Rng: 65W

Field Name: GREELEY Field Number: 32760  
Federal, Indian or State Lease Number:

Spud Date: (when the 1st bit hit the dirt) 06/06/2014 Date TD: 06/12/2014 Date Casing Set or D&A: 06/13/2014  
Rig Release Date: 06/14/2014 Per Rule 308A.b.

Well Classification:  
 Dry  Oil  Gas/Coalbed  Disposal  Stratigraphic  Enhanced Recovery  Storage  Observation

Total Depth MD 12381 TVD\*\* 6948 Plug Back Total Depth MD 12381 TVD\*\* 6948  
Elevations GR 4718 KB 4748 Digital Copies of ALL Logs must be Attached per Rule 308A

List Electric Logs Run:  
USIT, MUD, GR

CASING, LINER AND CEMENT

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
CONDUCTOR	17+1/2	16	42.05	0	130	88	0	130	VISU
SURF	13+3/4	9+5/8	36	0	665	340	0	665	VISU
1ST	8+3/4	7	26	0	7,323	605	575	7,323	CBL
1ST LINER	6+1/8	4+1/2	11.6	7192	12,366				

**STAGE/TOP OUT/REMEDIAL CEMENT**

Cement work date: \_\_\_\_\_

Method used	String	Cementing tool setting/perf depth	Cement volume	Cement top	Cement bottom

Details of work:

**FORMATION LOG INTERVALS AND TEST ZONES**

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analysis must be submitted to COGCC)
	Top	Bottom	DST	Cored	
PIERRE	1,072				
PARKMAN	3,639				
SUSSEX	4,175				
SHANNON	4,961				
TEEPEE BUTTES	6,004				
NIOBRARA	6,893				NBBR A 7098

Operator Comments

GPS TAKEN ON CONDUCTOR

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_

Print Name: Kathleen Mills

Title: Regulatory Analyst

Date: 10/28/2014

Email: kmills@nobleenergyinc.com

### Attachment Check List

Att Doc Num	Document Name	attached ?	
<b>Attachment Checklist</b>			
400719186	CMT Summary *	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Core Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
400719188	Directional Survey **	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	DST Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Logs	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Other	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
<b>Other Attachments</b>			
400718879	FORM 5 SUBMITTED	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400719004	CEMENT BOND	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400719023	MUD	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400719026	MUD	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400719171	MUD	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400719173	MUD	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400719189	DIRECTIONAL DATA	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400855997	GAMMA RAY	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400857186	PDF-GAMMA RAY	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400857189	PDF-GAMMA RAY	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineering Tech	PBTD adjusted to TD; liner not cemented. TVD rounded to nearest foot as per directional survey.	6/25/2015 7:59:30 AM
Permit	Two logs still have incorrect API number. Operator contacted. Returned to draft. Corrected Top of Production Zone (TPZ) footages to reflect directional survey reported values.	6/23/2015 7:47:45 AM
Permit	Well logs cite incorrect API number. Operator contacted. Returned to draft.	6/11/2015 8:54:57 AM

Total: 3 comment(s)