



photo 1: Beginning near New Elk 27-02 facing west along the access road towards New Elk 27-06.



photo 2: Access road facing west towards the location has recently been recontoured and reclaimed.



photo 3: Access road facing west towards the location has recently been recontoured and reclaimed.



photo 4: Areas of disturbance along the access road have been hydro seeded and mulched.



photo 5: Facing southwest along the reclaimed access road.



photo 6: Facing southwest along the reclaimed access road.



photo 7: Facing south towards the end of the reclaimed access road.



photo 8: New grass germination was noticed at this point along the reclaimed access road.