



photo 1: Beginning near New Elk 27-08 facing west along the access road towards New Elk 27-02.



photo 2: Access road facing west towards the location has recently been recontoured and reclaimed.



photo 3: Facing northwest along the reclaimed access road.



photo 4: Areas of disturbance along the access road have been hydro seeded and mulched.



photo 5: Facing northwest along the reclaimed access road.



photo 6: Facing west along the reclaimed access road near the New Elk 27-02 location.