

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400860070

Date Received:

06/29/2015

Spill report taken by:

YOUNG, ROB

Spill/Release Point ID:

440772

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>AUGUSTUS ENERGY RESOURCES LLC</u>	Operator No: <u>10489</u>	Phone Numbers
Address: <u>36695 HWY 385</u>		Phone: <u>(970) 332-3585</u>
City: <u>WRAY</u>	State: <u>CO</u>	Zip: <u>80758</u>
Contact Person: <u>Loni Davis</u>		Mobile: <u>()</u>
		Email: <u>ldavis@augustusenergy.com</u>

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400786068

Initial Report Date: 02/04/2015 Date of Discovery: 02/03/2015 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SWSW SEC 3 TWP 1S RNG 45W MERIDIAN 6Latitude: 39.991201 Longitude: -102.407003Municipality (if within municipal boundaries): _____ County: YUMA

Reference Location:

Facility Type: FLOWLINE☐ Facility/Location ID No _____☒ No Existing Facility or Location ID No.☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): >=5 and <100Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: CROP LAND

Other(Specify): _____

Weather Condition: Warm & WindySurface Owner: FEE

Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

the Poly pipe fuse broke, valves were shut to isolate the water, no surface water to recover, poly fuse was repaired. Size of area was approx 5' x 5'. Soil samples have been taken and will be submitted on a supplemental form 19 when received. As soon as analyses are received they will be reviewed and treated per the lab recommendations. The location will be strawed to help hold the moisture.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
2/3/2015	COGCC	Rob Young	-	Via e-mail - no response
2/3/2015	Yuma County	Kara Hoover	-	Via e-mail - no response
2/3/2015	Landowner	Wes & Pam Kiser	970-332-4255	Left Detailed message-no response

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 06/29/2015		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	15	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: _____

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) ☒ Soil ☐ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 42 Width of Impact (feet): 14

Depth of Impact (feet BGS): 6 Depth of Impact (inches BGS): 6

How was extent determined?

Visual observation

Soil/Geology Description:

8: Canyon-Dioxoce Complex 1-9% Slopes, 19: Haxtun Sandy Loam

Depth to Groundwater (feet BGS) 78 Number Water Wells within 1/2 mile radius: 1

If less than 1 mile, distance in feet to nearest

Water Well	<u>2449</u>	None <input type="checkbox"/>	Surface Water	<u> </u>	None <input checked="" type="checkbox"/>
Wetlands	<u> </u>	None <input checked="" type="checkbox"/>	Springs	<u> </u>	None <input checked="" type="checkbox"/>
Livestock	<u> </u>	None <input checked="" type="checkbox"/>	Occupied Building	<u> </u>	None <input checked="" type="checkbox"/>

Additional Spill Details Not Provided Above:

This spill was due to the poly fuse repair made in Feb. 2015 not holding together. The line was pressure tested at the time of repair. The fuse was repaired again on 6-25-15 and line was pressure tested again. Soil samples have been taken and submitted to the lab for analysis. When results are returned a remediation plan will be submitted along with the analysis. The information on the water well within the 1/2 mile radius was very sparse. The Depth to groundwater of 78 feet was taken from water well permit # 200688-A.

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☐ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Loni Davis

Title: Oper Acctg & Reg Spec Date: 06/29/2015 Email: ldavis@augustusenergy.com

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400860073	SITE MAP
400860074	AERIAL PHOTOGRAPH

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)