

## South Shale Ridge 7-24

Inspection# 675201794

Debris in tank containment  
noted on previous  
inspection.



Debris still in containment  
on follow up inspection

