



photo 1: Facing west along the access road towards the location.



photo 2: Facing west along the access road towards the location.



photo 3: Center of the location facing north.



photo 4: Center of the location facing west.



photo 5: Center of the location facing south.



photo 6: Center of the location facing east.



photo 7: Beginning of the vegetation transect facing southwest on the location (Disturbed).



photo 8: End of the vegetation transect facing northeast on the location (Disturbed).




photo 9: Beginning of the vegetation transect facing southeast on the location (Reference).



photo 10: End of the vegetation transect facing northwest on the location (Reference).