



Photo 1. View of western portion of project area from southwestern corner facing northward.



Photo 2. View of topsoil stockpile within southwestern portion of project area facing southward.





Photo 3. View of eastern portion of project area from southeastern corner facing northward.



Photo 4. View of project area from southeastern corner facing center.





Photo 5. View of northern portion of project area facing westward.



Photo 6. View of erosion from fill slope where sediment is washing over straw wattles in northern portion of project area.