

Bulldog 22-41V-890

Inspection# 673402288

Location overview taken
from NE corner of location.
No interim reclamation
apparent, weeds visible
around perimeter.



Location overview taken
from NE corner of location.
No interim reclamation
apparent, weeds visible
around perimeter.

