

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

07/27/2015

Document Number:

674701640

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335200	335200	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Compliance Summary:QtrQtr: NENW Sec: 28 Twp: 6S Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/15/2015	674701421			SATISFACTORY			No
01/22/2015	674700879			ACTION REQUIRED			No
05/15/2014	663903199			SATISFACTORY			No
01/22/2014	663902681			SATISFACTORY	I		No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
252	WELL	PR	03/27/2009	GW	045-15460	N. PARACHUTE MF02B C28 696	PR	<input checked="" type="checkbox"/>
253	WELL	PR	04/17/2009	GW	045-15461	N. PARACHUTE MF01A C28 696	PR	<input checked="" type="checkbox"/>
254	WELL	PR	04/17/2009	GW	045-15462	N. PARACHUTE MF01D C28 696	PR	<input checked="" type="checkbox"/>
255	WELL	PR	04/30/2009	GW	045-15463	N. PARACHUTE MF01C C28 696	PR	<input checked="" type="checkbox"/>
256	WELL	PR	03/31/2009	GW	045-15464	N. PARACHUTE MF02A C28 696	PR	<input checked="" type="checkbox"/>
258	WELL	PR	01/31/2009	GW	045-15465	N. PARACHUTE MF02D C28 696	PR	<input checked="" type="checkbox"/>
259	WELL	PR	04/14/2009	GW	045-15466	N. PARACHUTE MF01B C28 696	PR	<input checked="" type="checkbox"/>
260	WELL	PR	01/20/2009	GW	045-15467	N. PARACHUTE MF02C C28 696	PR	<input checked="" type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

291912	WELL	PR	04/14/2009	GW	045-14553	N. PARACHUTE MF15A-21 C28 69	PR	<input checked="" type="checkbox"/>
291915	WELL	PR	01/19/2009	GW	045-14552	N. PARACHUTE MF10A-21C28 696	PR	<input checked="" type="checkbox"/>
291916	WELL	PR	04/15/2009	GW	045-14551	N. PARACHUTE MF10B-21C28 696	PR	<input checked="" type="checkbox"/>
291918	WELL	PR	04/17/2009	GW	045-14550	N. PARACHUTE MF10C-21 C28 69	PR	<input checked="" type="checkbox"/>
291920	WELL	PR	04/30/2009	GW	045-14549	N. PARACHUTE MF10D-21 C28 69	PR	<input checked="" type="checkbox"/>
292039	WELL	PR	04/14/2009	GW	045-14554	N. PARACHUTE MF15B-21C28696	PR	<input checked="" type="checkbox"/>
293694	WELL	PR	04/17/2009	GW	045-15108	N. PARACHUTE MF15C-21 C28 69	PR	<input checked="" type="checkbox"/>
293695	WELL	PR	04/17/2009	GW	045-15109	N. PARACHUTE MF16C-21 C28 69	PR	<input checked="" type="checkbox"/>
425557	PIT		09/19/2011		-	C28 696		<input type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY			
DRILLING/RECOMP	SATISFACTORY	Ensign 325		
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: 1-800-791-7691

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Venting:**

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 335200

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____**Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____**Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 252 Type: WELL API Number: 045-15460 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 253 Type: WELL API Number: 045-15461 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 254 Type: WELL API Number: 045-15462 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID:	255	Type:	WELL	API Number:	045-15463	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	256	Type:	WELL	API Number:	045-15464	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	258	Type:	WELL	API Number:	045-15465	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	259	Type:	WELL	API Number:	045-15466	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	260	Type:	WELL	API Number:	045-15467	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	291912	Type:	WELL	API Number:	045-14553	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	291915	Type:	WELL	API Number:	045-14552	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	291916	Type:	WELL	API Number:	045-14551	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	291918	Type:	WELL	API Number:	045-14550	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	291920	Type:	WELL	API Number:	045-14549	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	292039	Type:	WELL	API Number:	045-14554	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	293694	Type:	WELL	API Number:	045-15108	Status:	PR	Insp. Status:	PR

Workover

Comment: Ensign rig 325 replacing tubing.

Facility ID: 293695 Type: WELL API Number: 045-15109 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Environmental**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? CM

CA CA Date

Waste Material Onsite? CM

CA CA Date

Unused or unneeded equipment onsite? CM

CA CA Date

Pit, cellars, rat holes and other bores closed? CM

CA CA Date

Guy line anchors removed? CM

CA CA Date

Guy line anchors marked? CM

CA CA Date

Inspector Name: LONGWORTH, MIKE

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Check Dams	Pass					
Berms	Pass					
Ditches	Pass					
Gravel	Pass					

Inspector Name: LONGWORTH, MIKE

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment:

CA:

Pits: ☒ NO SURFACE INDICATION OF PIT