

Inspector Name: Welsh, Brian

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE ET OE ES

Inspection Date:
07/29/2015Document Number:
679900090Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	228022	314204	Welsh, Brian	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 8005Name of Operator: BERRY ENERGY INC*WALTERAddress: 1717 WASHINGTON AVECity: GOLDEN State: CO Zip: 80401-

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Whiting, Jim	(719) 688-0064/ (505) 215-2474	jimwhiting_99@yahoo.com	All Inspections
Dennis, Penny	303-279- 0190/66190	berryenergy@comcast.net	

Compliance Summary:QtrQtr: SWNW Sec: 27 Twp: 25S Range: 45W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/18/2015	668501569	PR	PR	ACTION REQUIRED			No
04/09/2015	668501286	PR	PR	ACTION REQUIRED			No
01/16/2015	668500851	PR	PR	ACTION REQUIRED			No
06/24/2013	668600978	PR	PR	ACTION REQUIRED			No
02/13/2012	663900574	PR	SI	ALLEGED VIOLATION	P		Yes
03/15/2010	200235919	PR	PR	SATISFACTORY			No
06/11/2008	200190864	PR	PR	SATISFACTORY			No
05/10/2007	200110602	PR	PR	ACTION REQUIRED		Fail	Yes
08/13/1999	500156543	PR	PR			Pass	No
04/22/1997	500156542	PR	PR			Fail	Yes
06/07/1996	500156541	CC	DG			Pass	No

Inspector Comment:

STAINED SOIL HAS BEEN REMEDIATED, BERMS HAVE BEEN REPAIRED AND EROSION ON ACCESS HAS BEEN REPAIRED SINCE PREVIOUS INSPECTION

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
228022	WELL	PR	10/10/2006	GW	099-06349	DANIELS 1-27	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Inspector Name: Welsh, Brian

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY	DIRT ROAD THROUGH PASTURE. EROSION HAS BEEN REPAIRED		

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	LEASE SIGN MOUNTED ON METER SHED		
TANK LABELS/PLACARDS	SATISFACTORY	STICKERS ON PRODUCTION TANK		

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK BATTERY	SATISFACTORY	PIPE FENCE AROUND TANK HAS BEEN REPLACED WITH WIRE FENCE SINCE PREVIOUS INSPECTION		
SEPARATOR	SATISFACTORY	PIPE FENCE AROUND SEPARATOR		

Venting:

Yes/No	Comment
NO	

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 228022

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:S/A/V: SATISFACTORY **Comment:** NO COA'S

CA: _____ Date: _____

Wildlife BMPs:S/A/V: _____ **Comment:** _____

CA: _____ Date: _____

Stormwater:**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 228022 Type: WELL API Number: 099-06349 Status: PR Insp. Status: PR

Producing Well

Comment: PRODUCING. CASING PRODUCTION. NOT FLOWING AT TIME OF INSPECTION

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: Welsh, Brian

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Inspector Name: Welsh, Brian

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Compaction	Pass			

S/A/V: SATISFACTOR Y Corrective Date: _____

Comment: LOCATION IS GRASSED OVER. EROSION ON LEASE ROAD HAS BEEN REPAIRED

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
STAINED SOIL HAS BEEN REMEDIATED, BERMS HAVE BEEN REPAIRED AND EROSION ON ACCESS HAS BEEN REPAIRED SINCE PREVIOUS INSPECTION	welshb	07/29/2015