

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
07/30/2015

Document Number:
675201878

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>334443</u>	<u>334443</u>	<u>CONKLIN, CURTIS</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10433</u>
Name of Operator:	<u>PICEANCE ENERGY LLC</u>
Address:	<u>1512 LARIMER STREET #1000</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Bankert, Wayne	(970) 683-5419	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator
Arthur, Denise		denise.arthur@state.co.us	

Compliance Summary:

QtrQtr:	<u>SENE</u>	Sec:	<u>34</u>	Twp:	<u>9S</u>	Range:	<u>93W</u>
---------	-------------	------	-----------	------	-----------	--------	------------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/13/2015	675201433			SATISFACTORY			No
11/20/2014	675200808			SATISFACTORY			No
01/03/2013	668500270			SATISFACTORY	I		No

Inspector Comment:

Interim reclamation has taken place.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
285899	WELL	PR	06/29/2007	GW	077-09117	VEGA UNIT 34-431	PR	<input checked="" type="checkbox"/>
286493	WELL	PR	08/24/2007	GW	077-09134	VEGA UNIT 34-421	PR	<input checked="" type="checkbox"/>
286494	WELL	PR	05/03/2008	GW	077-09133	VEGA UNIT 34-321	PR	<input checked="" type="checkbox"/>
286495	WELL	PR	07/08/2007	GW	077-09132	VEGA UNIT 34-414	PR	<input checked="" type="checkbox"/>
286496	WELL	PR	08/09/2007	GW	077-09131	VEGA UNIT 34-411	PR	<input checked="" type="checkbox"/>
286497	WELL	PR	04/16/2008	GW	077-09130	VEGA UNIT 34-311	PR	<input checked="" type="checkbox"/>
286498	WELL	PR	08/24/2007	GW	077-09129	VEGA UNIT 34-314	PR	<input checked="" type="checkbox"/>
286499	WELL	PR	09/28/2009	GW	077-09128	VEGA UNIT 34-324	PR	<input checked="" type="checkbox"/>

286528	WELL	PR	07/05/2007	GW	077-09135	VEGA UNIT 34-424	PR	<input checked="" type="checkbox"/>
286529	WELL	PR	01/09/2008	GW	077-09136	VEGA UNIT 34-331	PR	<input checked="" type="checkbox"/>
293460	WELL	PR	11/14/2007	GW	077-09452	VEGA FEDERAL 34-224	PR	<input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 334443

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 285899 Type: WELL API Number: 077-09117 Status: PR Insp. Status: PR

Producing Well

Comment: **PR**

Facility ID: 286493 Type: WELL API Number: 077-09134 Status: PR Insp. Status: PR

Producing Well

Comment: **PR**

Facility ID: 286494 Type: WELL API Number: 077-09133 Status: PR Insp. Status: PR

Producing Well

Comment: **PR**

Facility ID: <u>286495</u>	Type: <u>WELL</u>	API Number: <u>077-09132</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: PR				
Facility ID: <u>286496</u>	Type: <u>WELL</u>	API Number: <u>077-09131</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: PR				
Facility ID: <u>286497</u>	Type: <u>WELL</u>	API Number: <u>077-09130</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: PR				
Facility ID: <u>286498</u>	Type: <u>WELL</u>	API Number: <u>077-09129</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: PR				
Facility ID: <u>286499</u>	Type: <u>WELL</u>	API Number: <u>077-09128</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: PR				
Facility ID: <u>286528</u>	Type: <u>WELL</u>	API Number: <u>077-09135</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: PR				
Facility ID: <u>286529</u>	Type: <u>WELL</u>	API Number: <u>077-09136</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: PR				
Facility ID: <u>293460</u>	Type: <u>WELL</u>	API Number: <u>077-09452</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: PR				

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: 07/23/2015 Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Contractor was just finishing track walking slopes at time of inspection.

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? In Production areas stabilized? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____
 Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Gravel	Pass					
Berms	Pass	Compaction	Pass			

S/A/V: SATISFACTOR
 Y
 Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675201882	Slope	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3654799
675201883	Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3654800