



Photo # 1 : Russian Knapweed establishing in berms.



Photo #2 : Looking SE on access road into Location. Kochia lining roadway ditches.



Photo # 3 : Looking SW along Location berm supporting Kochia infestation.



Photo # 4 : Looking from NW corner of location along berm, stormwater ditch and sediment trap overwhelmed by Kochia growth.