



EROSION AND DEEP TRACKS ON ACCESS TO
LOCATION



EROSION LEADING
ONTO LOCATION
NEEDS REPAIRED

GRAVEL ADDED
TO LOCATION
ENTRANCE
EROSION

A photograph of a dirt road in a grassy field. The road has deep tracks and erosion, particularly on the left side. The vegetation consists of low-lying green shrubs and grasses. The sky is clear and blue.

EROSION AND DEEP TRACKS ON
ACCESS TO LOCATION NEEDS
REPAIRED

RILLING EROSION FROM PASTURE
LEADING ONTO LOCATION NEXT TO
ENTRANCE

