



Photo #1: View of Location from SW corner



Photo #2 View of area, appears to have been seeded Fall of 2014. Wheat appearing to be the dominant species, though Wheatgrass, barley and Alfalfa are also evident





Photo 3: Gully formed from stormwater runoff.



Photo # 4: Erosion and run off channel forming on center N edge of pad





Photo # 5 Erosion on NE edge where wash out of seeded area is evident



Photo # 6 : BMP not functioning on Eastern edge of location





Photo # 7: Gravel pile on NW corner of location.