



View of location from pad entry looking SE.



Rock retaining wall and interim reclamation

August 4, 2015

Inspection Photos Loc# 335428



Interim reclamation looking NE from N edge of pad.