



**photo 1:** Standing from the main access road facing north towards the reclaimed access road.



**photo 2:** Facing north along the reclaimed access road. Vegetation along the initial 200' of access road has not established as well as the rest of the reclaimed access road.



photo 3: : Areas of the initial 200' of access road seem to have compacted soils.



photo 4: Facing northwest along the reclaimed access road.



**photo 5:** Facing back towards the southeast along the reclaimed access road.



**photo 6:** Facing northwest along the reclaimed access road.



**photo 7:** Facing southwest towards the reclaimed access road where vegetation is establishing.



**photo 8:** Facing east towards the location from the access road.