



Photo 1: View from access rd. Looking West to center of Location



Photo 2: Musk thistle, B List State and County Noxious Weed established on SE berm area.





Photo 3: Open pit at West end of location.



Photo 4: Stormwater BMPs in need of maintenance





Photo #5: Cut slope at North side of Location. Rill erosion and sediment run on



Photo #6 : Fill slope at West end of Location. Canada, Musk thistle and erosion





Photo #7: Conductor Set on Well # 05-077-10165. B List Noxious Weeds establishing in Well Pad area.