

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:  
08/11/2015Document Number:  
680100078

Overall Inspection:

**ACTION REQUIRED****FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335550	335550	Colby, Lou	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 602 SAWYER STREET #710City: HOUSTON State: TX Zip: 77007

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-372-5706	dknudson@ursaresources.com	Senior Environmental Specialist - Piceance
Bleil, Rob	970-329-4373	rbleil@ursaresources.com	Ursa Regulatory & Environmental Manager
Freeman, Sarah		sarah.freeman@state.co.us	XX permit Expired

**Compliance Summary:**QtrQtr: SWNE Sec: 18 Twp: 6S Range: 92W**Inspector Comment:****Reclamation and stormwater focused inspection. Six XX Wells have expired permits, of those, four with Conductors set.****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
293098	WELL	PR	12/14/2012	GW	045-14882	DIXON A8	PR	<input checked="" type="checkbox"/>
293099	WELL	XX	10/05/2011	LO	045-14883	DIXON A7	TA	<input checked="" type="checkbox"/>
293100	WELL	PR	10/15/2012	GW	045-14884	DIXON A3	PR	<input checked="" type="checkbox"/>
293101	WELL	PR	09/13/2012	GW	045-14885	DIXON A2	PR	<input checked="" type="checkbox"/>
293102	WELL	PR	12/14/2012	GW	045-14886	DIXON A1	PR	<input checked="" type="checkbox"/>
293103	WELL	XX	03/14/2014	LO	045-14887	Dixon A4	XX	<input checked="" type="checkbox"/>
293104	WELL	PR	12/14/2012	GW	045-14888	DIXON A5	PR	<input checked="" type="checkbox"/>
293105	WELL	PR	12/14/2012	GW	045-14889	DIXON A6	PR	<input checked="" type="checkbox"/>
293106	WELL	PR	09/12/2012	GW	045-14890	DIXON A9	PR	<input checked="" type="checkbox"/>
293151	WELL	XX	10/05/2011	LO	045-14900	DIXON A16	XX	<input checked="" type="checkbox"/>

Inspector Name: Colby, Lou

293152	WELL	XX	10/05/2011	LO	045-14901	DIXON A15	XX	<input checked="" type="checkbox"/>
293153	WELL	XX	10/05/2011	LO	045-14902	DIXON A14	XX	<input checked="" type="checkbox"/>
293154	WELL	XX	10/05/2011	LO	045-14903	DIXON A12	XX	<input checked="" type="checkbox"/>
293156	WELL	XX	10/05/2011	LO	045-14904	DIXON A13	XX	<input checked="" type="checkbox"/>
293157	WELL	PR	12/14/2012	GW	045-14905	DIXON A11	PR	<input checked="" type="checkbox"/>
293158	WELL	XX	10/05/2011	LO	045-14906	DIXON A10	XX	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

Emergency Contact Number (S/A/V): \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WEEDS	ACTION REQUIRED	Kochia infestation will become debris if not controlled	Control weeds.	09/04/2015
DEBRIS	ACTION REQUIRED	Kochia will become debris and blow, infecting adjacent properties.	Control weeds.	09/04/2015

**Spills:**

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

**Equipment:**

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Other		ACTION REQUIRED	Cellar grates (covers) askew, not in position to minimize adverse impacts to workplace safety and wildlife. Refer to photos attached.	Adjust, install cellar covers to maximize safety and wildlife welfare.	08/27/2015

<b>Venting:</b>		
Yes/No	Comment	

<b>Flaring:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 335550

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 293098 Type: WELL API Number: 045-14882 Status: PR Insp. Status: PR

Facility ID: 293099 Type: WELL API Number: 045-14883 Status: XX Insp. Status: TA

Inspector Name: Colby, Lou

Facility ID:	293100	Type:	WELL	API Number:	045-14884	Status:	PR	Insp. Status:	PR
Facility ID:	293101	Type:	WELL	API Number:	045-14885	Status:	PR	Insp. Status:	PR
Facility ID:	293102	Type:	WELL	API Number:	045-14886	Status:	PR	Insp. Status:	PR
Facility ID:	293103	Type:	WELL	API Number:	045-14887	Status:	XX	Insp. Status:	XX
Facility ID:	293104	Type:	WELL	API Number:	045-14888	Status:	PR	Insp. Status:	PR
Facility ID:	293105	Type:	WELL	API Number:	045-14889	Status:	PR	Insp. Status:	PR
Facility ID:	293106	Type:	WELL	API Number:	045-14890	Status:	PR	Insp. Status:	PR
Facility ID:	293151	Type:	WELL	API Number:	045-14900	Status:	XX	Insp. Status:	XX
Facility ID:	293152	Type:	WELL	API Number:	045-14901	Status:	XX	Insp. Status:	XX
Facility ID:	293153	Type:	WELL	API Number:	045-14902	Status:	XX	Insp. Status:	XX
Facility ID:	293154	Type:	WELL	API Number:	045-14903	Status:	XX	Insp. Status:	XX
Facility ID:	293156	Type:	WELL	API Number:	045-14904	Status:	XX	Insp. Status:	XX
Facility ID:	293157	Type:	WELL	API Number:	045-14905	Status:	PR	Insp. Status:	PR
Facility ID:	293158	Type:	WELL	API Number:	045-14906	Status:	XX	Insp. Status:	XX

### Environmental

#### Spills/Releases:

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

#### Water Well:

Lat \_\_\_\_\_ Long \_\_\_\_\_  
DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

#### Field Parameters:

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: **The majority of vegetation within the interim reclamation area is Kochia.**

1003a. Debris removed? Pass CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Waste Material Onsite? Pass CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? Pass CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? Fail Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? FailProduction areas have been stabilized? Pass

Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**CroplandTop soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established FailNon-CroplandTop soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation Fail

1003 f. Weeds Noxious weeds? \_\_\_\_\_ I \_\_\_\_\_

Comment: **No desirable species establishing. Interim Reclamation not progressing. Refer to Overall status and photos attached. CA is to revegetate interim reclamation area; reclamation activities complete by end of Fall 2015.**Overall Interim Reclamation Fail**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Inspector Name: Colby, Lou

Debris removed _____	No disturbance /Location never built _____
Access Roads _____	Regraded _____
Gravel removed _____	Contoured _____
_____	Culverts removed _____
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____
Compaction alleviation _____	Dust and erosion control _____
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
Comment: _____	
Corrective Action: _____	Date _____
Overall Final Reclamation _____	Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/>

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: SATISFACTOR Y \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Pits: ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
No desirable perennial vegetation was observed establishing in the interim reclamation area. Kochia, Cheat grass and Wheat make up the majority of the plant community. Action Required is to revegetate Interim Reclamation area; reclamation activities to be complete by end of Fall 2015.	colbyl	08/18/2015
Deveolpment of monitoring and action plan for interim reclamation sites, especially in years favoring weed growth may be benifical for operator.		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680100083	Ursa Dixon pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3665877">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3665877</a>

## **ACTION REQUIRED**

**ANY ACTION REQUIRED** items listed on this report indicate that the oil and gas facility or the oil and gas operations listed on the report may be in violation of the rules and regulations of the Colorado Oil and Conservation Commission (“COGCC”) and corrective action is required.

There is reasonable cause to believe that a violation of the Oil and Gas Conservation Act, or of any rule, regulation, or order of the Commission, or of any permit issued by the Commission, has occurred. The Operator’s compliance with this Inspection Report is required to resolve these alleged violations. This document requires the Operator to timely respond to the COGCC and to comply with directives as listed by the **Corrective Action Deadline Date**. Failure to do so will result in the issuance of a Notice of Alleged Violation and initiation of enforcement proceedings in which COGCC will seek monetary penalties for the alleged violations pursuant to § 34-60-121, C.R.S. and Rule 523, COGCC Rules of Practice and Procedure, 2 CCR 404-1. (Please note that the COGCC's penalty authority was recently increased to a maximum of \$15,000 per day and penalties are no longer capped at a maximum of \$10,000 per violation.)