

GLADE* CHRIS OIL & GAS LLC -
10378

MANHATTAN FEDERAL #1A

05-103-07875

8/20/2015

by Kyle P Granahan



Stained soil at wellhead – initial inspection



Stained soil at wellhead – follow up inspection



Incomplete battery sign – initial inspection



Incomplete battery sign – follow up inspection



Empty drum – initial inspection



Empty drum – follow up inspection



Tank labels missing – initial inspection



Tank labels missing – follow up inspection