

GLADE* CHRIS OIL & GAS LLC -
10378

WOLF #1

05-103-07462

8/20/2015

by Kyle P Granahan



Incomplete battery sign – initial inspection



Incomplete battery sign – follow up inspection



Tank not in use – initial inspection



Tank not in use – follow up inspection



No well sign – initial inspection



No well sign – follow up inspection



Tubing, rod, and drum – initial inspection



Tubing, rod, and drum – follow up inspection



Tubing and rod – initial inspection



Tubing and rod – follow up inspection



Tanks not labeled and drums – initial inspection



Tanks not labeled and drums – follow up inspection



Tanks not labeled and drums – initial inspection



Tanks not labeled and drums – follow up inspection



Drum – initial inspection



Drum – follow up inspection



Additional drum – follow up inspection



Pit on location

Pit was snowed over and covered during initial inspection



Pit on location



Pit on location



Google earth view of pit on location.