

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:
08/20/2015Document Number:
671104804Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	442647	302423	MONTOYA, JOHN	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
,		COGCCinspections@anadarko.com	All Inspections
REDDY, LUKE		Luke.Reddy@anadarko.com	ALL INSPECTIONS

Compliance Summary:QtrQtr: NENE Sec: 22 Twp: 2N Range: 65W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
298564	WELL	PR	11/20/2009	OW	123-29100	ROBERT POWERS X 22-27	SI	<input checked="" type="checkbox"/>
442644	WELL	XX	07/27/2015		123-41950	POWERS 2N-27HZ	ND	<input checked="" type="checkbox"/>
442645	WELL	XX	07/27/2015		123-41951	POWERS 1N-27HZ	ND	<input checked="" type="checkbox"/>
442646	WELL	XX	07/27/2015		123-41952	POWERS 1C-27HZ	ND	<input checked="" type="checkbox"/>
442647	WELL	XX	07/27/2015		123-41953	POWERS 27N-27HZ	ND	<input checked="" type="checkbox"/>
442648	WELL	XX	07/27/2015		123-41954	POWERS 2G-27HZ	ND	<input checked="" type="checkbox"/>
442649	WELL	XX	07/27/2015		123-41955	POWERS 2C-27HZ	ND	<input checked="" type="checkbox"/>
442650	WELL	XX	07/27/2015		123-41956	POWERS 26N-27HZ	ND	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>8</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: <u>7</u>
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Inspector Name: MONTOYA, JOHN

Location

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 442647

Site Preparation:

Lease Road Adeq.: SATISFACTORY

Pads: SATISFACTORY

Soil Stockpile: SATISFACTORY

S/A/V: SATISFACT

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
OGLA	treitzr	Operator shall provide notice to COGCC 48 hours prior to commencing construction of this Oil and Gas Location via Form 42 per Rule 316C.c.	07/21/2015

S/A/V: SATISFACTORY**Comment:** top soil pile east of pad**CA:** _____ **Date:** _____**Wildlife BMPs:**

BMP Type	Comment
Planning	This proposed oil and gas location is located in a rural rangeland area. The nearest building unit is located 3167' away.

S/A/V: SATISFACTORY**Comment:** BMP's in place**CA:** _____ **Date:** _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
DITCHES	Yes	Self Inspection	Yes`

S/A/V: _____

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: erosion BMP's in place**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**

Facility

Facility ID: 298564 Type: WELL API Number: 123-29100 Status: PR Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

S/A/V: SATISFACTORY CA Date: _____

CA: _____

Comment: well is SI for horizontal prep

Facility ID: 442644 Type: WELL API Number: 123-41950 Status: XX Insp. Status: ND

Well Drilling**Rig:** Rig Name: _____ Pusher/Rig Manager: _____

Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____

Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____

Multi-Well: _____ Disposal Location: _____

Comment:

not drilled yet

Facility ID: 442645 Type: WELL API Number: 123-41951 Status: XX Insp. Status: ND

Well Drilling**Rig:** Rig Name: _____ Pusher/Rig Manager: _____

Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____

Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____

Multi-Well: _____ Disposal Location: _____

Comment:

not drilled yet

Facility ID: 442646 Type: WELL API Number: 123-41952 Status: XX Insp. Status: ND

Well Drilling**Rig:** Rig Name: _____ Pusher/Rig Manager: _____

Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____

Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Inspector Name: MONTOYA, JOHN

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
Multi-Well: _____ Disposal Location: _____

Comment:

not drilled yet

Facility ID: 442647 Type: WELL API Number: 123-41953 Status: XX Insp. Status: ND

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
Multi-Well: _____ Disposal Location: _____

Comment:

not drilled yet

Facility ID: 442648 Type: WELL API Number: 123-41954 Status: XX Insp. Status: ND

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
Multi-Well: _____ Disposal Location: _____

Comment:

not drilled yet

Facility ID: 442649 Type: WELL API Number: 123-41955 Status: XX Insp. Status: ND

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
Multi-Well: _____ Disposal Location: _____

Comment:

not drilled yet

Facility ID: 442650 Type: WELL API Number: 123-41956 Status: XX Insp. Status: ND

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment:

not drilled yet

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Inspector Name: MONTOYA, JOHN

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Gravel	Pass			

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
location has been built BMP's in order around location pilot holes for surface casing have been drilled and set with culverts in place	montoyaj	08/20/2015

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
671104805	well marker	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3666497
671104807	well markers and surface holes have been drilled for drilling rig foe surface casing	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3666498
671104808	BMP's around location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3666499
671104809	top soil pile	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3666500