



Photo#1: Entrance to Location



Photo# 2: View to SW of Location showing areas no longer needed for use, not reclaimed.



Photo# 3: View to NE of Location showing areas no longer needed for use, not reclaimed.



Photo# 4 : View of SW corner of Location where Livestock or Wildlife traffic is impinging on integrity of Cut slope.



Photo# 5 Guy Anchors not removed.



Photo# 6: Drains need maintenance and to be more efficiently installed.